


Note:

1. Trim Off All Dead Fronds, Flower Stalks and Fruits Prior to Planting
2. Tip Prune Excessively Long Individual Fronds
3. Do Not Break Terminal Bud
4. Scarify All Sides of Planting Pit
5. Remove All PVC Pipe & Guy Wires When Tree is Well Established and Supports Are No Longer Needed



L-7(F)

CITY COUNTY OF HONOLULU

**COCONUT PALM RELOCATING
AND PLANTING DETAIL**

SCALE: NOT TO SCALE

REVISED: APRIL 2003

STANDARD
DETAILS

L-7